

ACCESSORIES AND REPLACEMENT PARTS:

Description	Part Number
Probe Mounting Kits Wastewater submersion - galvanized iron fittings for 1-1/2" pipe handrail mounting	31063324-501
Pure water, flow through -1/4" OD tube connections - For SS Probe: For PVC Probe:	51452187-501 51452187-502
Process, in-line to mount directly in the sample line with 3/4" NPT tap - For SS Probe: For PVC Probe:	51452226-501 51452226-502
Extension Cables for Sensors with Quick Disconnect Option: 2m (6.56 ft.) 3m (9.84 ft.) 6m (19.69 ft.) 15m (49.21 ft.) 30m (98.43 ft.) <i>Only Honeywell Extension Cables can be used</i>	50024092-501 50024092-502 50024092-503 50024092-504 50024092-505
Replacement O-ring for in-line and flow-through mounting	30669860-517
Junction Box, cast iron 3/4" NPT	31316260-501
Extension cable 26 gage, 5-conductor, shielded (specify length) 7.62m (25 ft.) length 15.24m (50 ft.) length 22.87m (75 ft.) length 30.48m (100 ft.) length	51452215-501 51452215-502 51452215-503 51452215-504

Note 1: For PPB (typically power utility and semi-conductor water quality application)
Order Accessory Part #51452187-501 (SS) or -502 (PVC) pure water flow
through kit to ensure air free sample to probe.

Note 2: Please order corresponding Quick Disconnect sensor-to-instrument cable from accessory table.